


WHITE WIRE from the power supply
goes on L1.
(Top Terminal next to unloader)

BLACK WIRE from Power supply
goes on L2.
(Top Terminal next to Red On/Off Lever)



WHITE WIRE to Motor goes on T1.
(Bottom Terminal)

BLACK WIRE from Motor goes on T2.
(Bottom Terminal)